Ted Stevens Anchorage International Airport - Taxiway E and M Reconstruction					FY2013 Request: Reference No:			4,000,000\$ 49094
AP/AL: Allocation				Project Type: Construction				
Category: 7	Fransportation			-				
Location: Anchorage Areawide				House District: Anchorage Areawide (HD 17- 32)				
Impact Hou 17-32)	ISE District: And	chorage Areav	vide (HD	Contact: Steve Hatter				
Estimated	Project Dates: (07/01/2012 - 0	6/30/2019	Contact	Phone: (907)269-07	730	
	on: Airport Impro				· ·	,		
at the Taxiwa Taxiway E w is 51. Any Pe	Taxiway E from ay E and L inters yest to Taxiway F CI below 55 is co the taxiways may <u>FY2013</u> \$3,750,000 \$250,000	section. This p R. Taxiway E F onsidered poo	project also Pavement C r and in nee	includes re Condition I	econstruction ndex (PCI) is	n at Tax 50 and avemen	iway M I Taxiw	1 from vay M PCI
Total:	\$4,000,000	\$0	\$0	\$0	\$0		\$0	\$4,000,000
			PhasedAmendr		Phased - u		🗆 On	-Going
Operating 8	& Maintenance (Costs:			Ar	nount		Staff
			oject Develo	opment:		0		0
			Dngoing Op	•		0		0
			One-Time	•		0		
				Totals:		0		0

Additional Information / Prior Funding History:

\$15,000,000 - Ch 5 FSSLA 2011 Pg 108 ln 26; \$20,000,000 - Ch 43 SLA 2010 Sec 7 pg 43 ln 12.

Project Description/Justification:

The reconstructions consist of excavating the existing structural section and replacing with structural section that is designed for the current aircraft mix that use the taxiway.

Taxiway E and Taxiway M are part of the main movement areas at Anchorage International Airport. Taxiway E is showing signs of advanced structural failure. There is alligator cracking occurring along the majority of both taxiways. Field Maintenance has to perform yearly pavement repairs (peel and pave). While this work helps keep taxiways open it does not fix the root cause of the pavement failure. The structural section was not designed for the current mix or volume of aircraft.

The Federal Aviation Administration (FAA) requires that airports have a Pavement Management System (AC 150/5380-7) that facilitates identification of expected pavement needs. ANC's Pavement Management System identifies pavement condition as a function of the PCI. The PCI is established through a survey and subsequent software analysis of asphalt and concrete pavement condition. The State of Alaska Capital Project Summary Department of Transportation/Public Facilities FY2013 Governor Reference No: 49094 12/15/11 2:06:45 PM Page 1 Released December 15th, 2011

Ted Stevens Anchorage International Airport - Taxiway E and M Reconstruction

PCI is a metric value of 0-100, with 100 being the optimum pavement condition. The pavement condition surveys analyze cracks, spalling, rutting, and other pavement conditions that become part of the 0-100 metric. Poor pavement conditions result in Foreign Object Debris (FOD) on aprons, runways and taxiways and are safety concerns for aircraft moving on the airfield. A PCI condition below 60 is an indication that a project should be programmed in the short term to rehabilitate taxiways and aprons and existing paved airfield surfaces.

The existing asphalt at Taxiways E and M is in poor condition. It has a PCI of 50 at Taxiway E and a PCI of 51 at Taxiway M. This is less than the desired minimum required under the Pavement Maintenance and Management Plan. The aprons are cracking, deteriorating, and fail to meet minimum Pavement Condition Index requirements. Existing pavement cracks will grow and expand, leading to pavement failures within the Taxiway's surface. This involves potential damage to aircraft and surface transportation vehicles from cracks, ruts, FOD and other impediments.

This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.