Haines Highway Milepost 19 - 23 Rock Slide Emergency FY2012 Request: \$150,250 Repairs Reference No: 48805

AP/AL: Allocation **Project Type:** Construction

Category: Transportation

Location: Haines House District: Cordova/Southeast Islands

(HD 5)

Impact House District: Cordova/Southeast Islands Contact: Pat Kemp

(HD 5)

Appropriation: Emergency Repairs

Brief Summary and Statement of Need:

On September 6, 2011 a rock slide deposited approximately 15,000 yards of rock and debris on the Haines Highway at mile post (MP) 19. The heavy rains on September 6 also caused a smaller rock slide at MP 23 of the Haines Highway. Approximately 5,000 yards of rock and debris was deposited into the right of way and one lane of the highway. This funding would reimburse the department for costs incurred during the emergency repairs done on the Haines Highway during this incident.

Funding:	FY2012	FY2013	FY2014	FY2015	FY2016	FY2017	<u>l otal</u>	
Gen Fund	\$150,250						\$150,250	
Total:	\$150,250	\$0	\$0	\$0	\$0	\$0	\$150,250	
☐ State Match Required ☐ One-Time Project ☐ Phased - new					Phased - under	•	✓ On-Going	
0% = Minimur	n State Match % R	equired	L Amendn	nent	☐ Mental Health	Bill		
Operating & Maintenance Costs:					Amou	Amount Staff		
Project Development:					0	0		
Ongoing Operating:				erating:		0 0		
	One-Time Startup:					0		

Totals:

Additional Information / Prior Funding History:

Haines Highway MP 19 Emergency Funding \$89,700 - Ch 5, Sec 13, SLA 2011, page 155, line 14; \$80,000 - Ch 43, Sec 1, SLA 2010, page 5, line 21

Project Description/Justification:

On September 6, 2011 a rock slide deposited approximately 15,000 yards of rock and debris on the Haines Highway at Mile Post (MP) 19. This portion of the highway crosses an alluvial fan and is a location of perennial slides. The Southeast Region Maintenance Crew was able to re-open the highway to traffic and has cleaned the debris from the right of way, culverts and spillways and reestablished sumps and diversion berms.

The heavy rains on September 6 also caused a smaller rock slide at MP 23 of the Haines Highway. Approximately 5,000 yards of rock and debris was deposited into the right of way and one lane of the highway. The Southeast Region Maintenance crew also performed emergency repairs and debris removal from the right of way from this section of highway.

0