Cold Bay - Runway 14/32 Rehabiltiaton with Lighting FY2013 Request: \$16,000,000 System Replacement Reference No: 36289 AP/AL: Allocation **Project Type:** Construction **Category:** Transportation Location: Cold Bay **House District:** Bristol Bay/Aleutians (HD 37) Impact House District: Bristol Bay/Aleutians (HD **Contact:** Steve Hatter 37) Estimated Project Dates: 07/01/2012 - 06/30/2019 Contact Phone: (907)269-0730 **Appropriation:** Airport Improvement Program **Brief Summary and Statement of Need:** Rehabilitate the main runway, install new edge lighting. Funding: FY2013 FY2014 FY2015 FY2016 FY2017 FY2018 Total Fed Rcpts \$16,000,000 \$16,000,000 \$0 Total: \$16,000,000 \$0 \$0 \$0 \$16,000,000 ✓ State Match Required ✓ One-Time Project Phased - new Phased - underway ☐ On-Going 5% = Minimum State Match % Required Amendment **Operating & Maintenance Costs: Amount** Staff Project Development: 0 0 Ongoing Operating: 0 0 One-Time Startup: 0 0 n Totals:

Additional Information / Prior Funding History:

None.

Project Description/Justification:

This project is needed due to the general pavement condition at the airport, and the age of the lighting system. The Pavement Condition Index (PCI) shows the pavement being below standards (it is between 55 and 69 on the PCI scale and should be 70 or above), the lighting is old and in need of replacement.

This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.