Bethel Armory Deferred Maintenance

FY2013 Request: Reference No:

\$340,000 54806

AP/AL: Allocation Project Type: Deferred Maintenance

Category: Public Protection

Location: Bethel House District: Bethel (HD 38)

Impact House District: Bethel (HD 38) Contact: McHugh Pierre

Appropriation: Deferred Maintenance, Renewal, Repair and Equipment

Brief Summary and Statement of Need:

The Bethel Armory needs to repair/replace the existing fence and hangar apron. These deferred maintenance projects address issues of life safety and code compliance.

Funding:	FY2013	FY2014	FY2015	FY2016	FY2017	FY2018	Total
Fed Rcpts G/F Match	\$280,000 \$60,000		\$25,000 \$25,000	\$100,000			\$405,000 \$85,000
Total:	\$340,000	\$0	\$50,000	\$100,000	\$0	\$0	\$490,000

□ State Match Required □ One-Time Pro	ject ∟ Phased - new	□ Phased - underway	✓ On-Going	
0% = Minimum State Match % Required	Amendment	□ Mental Health Bill		
Operating & Maintenance Costs:		<u>Amount</u>	Staff	
	Project Development:	0	0	
	Ongoing Operating:	0	0	
	One-Time Startup:	0		

Totals:

Additional Information / Prior Funding History:

See deferred maintenance appropriation.

Project Description/Justification:

The Bethel Armory needs to repair/replace the existing fence to meet mandatory federal security requirements. The aircraft apron at the Army National Guard Hangar located at the airport also needs crack-seal and other preventative maintenance. Priorities and cost estimates may need to be changed to accommodate emergency maintenance projects not listed, actual project costs, and other considerations.

Project Titles	Federal	G/F Match	Project Description
Bethel Armory –	\$60,000	\$60,000	Repair/replace existing fence to
02A60-0001 & 0004 -			meet federally mandated security
repair/replace existing			requirements at the Bethel
fence			Armory complex.
Bethel Armory –	\$220,000	\$0	Provide crack-seal and other
02A65-0002 - repair			preventative maintenance to
hangar apron			aircraft apron concrete.

FY2013 Request: Reference No:

\$340,000 54806